

This policy applies to all manufactured or industrialized buildings set-up within the County. The intent is to insure that all connections are properly made.

Notice
**Special Inspection
Required
2006 USBC 113.4
Marriage Connections**

This permit requires special inspection per 2006 USBC Section 113.4. All marriage connections must be inspected before concealment. This includes required connections between roof sections, wall sections and floor sections. Marriage connections concealed without inspection will not be approved and areas will be required to be re-exposed at the permit holders expense.

A copy of the manufacturers setup and / or assembly instructions must be available at the time of inspection. The permit holder must also provide a safe access to the roof and or attic if applicable. Inspectors will not provide ladders or climb unsafe ladders.

To schedule an inspection call 757-678-0445. A 48 hour (two working days) notice may be necessary for an inspection. (This time frame may be less depending upon the County's work load.)